Work Ord March 10, 2010	er ID 56844 3:53:24 PM	PSAD									Page 1
Item ID: Revision ID:	D3805-043		Accept					Setup	Start		
Item Name:	Wearplate Assembly Fwd, High Gear	12							Stop		
Start Date: Required Date: Reference:	10/03/2010 Start Qty: 2.00 17/03/2010 Req'd Qty: 2.00		·	Cust Item 1 Customer:	ID:						
Approvals:	Process Plan:QC:	Date:	Tooling: _ SPC (Y/N):		ate:			Run	Start Stop		And of the control of
Sequence ID/ Work Center II	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr	r				•					\$1
D3805	Rev A										ķ
100 Large Fab Large Fab	Memo 1- on D380	5-3, fill cut outs with hardc	0.00 0.00 oat welding rod as per d	wa D3805			R		16-9	4-29	(x5)
	2059 B H BATCH#	ardcoat Welding Rod	out wording for as per u	wg 155005							
	304 S.S.	Welding Rod Word Market Street Stree	ioning holes together as	per dwg D3805							
	3-Transfer of	Irill holes in bar									
	QC9- Inspect visual per	QSI004- Fusion Welds	0.00				(3)	δP '	000	3.O.S.	in the second se
QC Quality Control	Memo		0.00								-

Da	rt /	Aero	spa	ce	Ltd

	-											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CHAN	NGE		Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector			
			,									
Part No		PAR #:					• .					
Resolution:		esolution:	Disposition):	QA	: N/C Clo	sed:	Date: _				
NCR:		1	WORK ORDE	R NON-CONF	ORMANC	(NCR)					
DATE	STEP	Description of NC		Corrective Action	Section B	Sign &	Verification	on Approval	Approval			
DAIL	JILF	Section A	Initial Chief Eng	Action Descri Chief Eng	Action Description Chief Eng		Section C		QC Inspector			
									-			
			·	· · · · · · · · · · · · · · · · · · ·								
					·							
									1			

Work Order ID 56844

March 10, 2010 3:53:24 PM

Required Date: 17/03/2010



Page 2

Item ID:

D3805-043

Accept

Setup Start



Revision ID:

Item Name:

Wearplate Assembly Fwd, High Gear

Start Date:

10/03/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Tooling:

Date:

Run

Start

Stop



Date:____

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID**

120



Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours** Draw Number

Draw Plan Rev. Code

Accept Qty

Reject **Qty**

Reject Insp. Number Stamp

Memo

8 volos/or

0.00 7 9 10/05/07

130



Powdercoat

Powder Coating

Grey Sandtex(Ref:4.3.5.6) per QS1005 4.3

Memo

START TIME: 7:00AM

OVEN TEMPERATURE: 370°F FINISH TIME: 7.30°

140



Quality Control

QC3- Inspect Part Finish

Memo

0.00

0.00

0.00

5 BR 10-5-7

	-								
W/O:			WC	RK ORDER CHAN	GES				
DATE	STEP	PR	OCEDURE CHA		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	s No DQ	A:	Date:	
Resol		solution:							
NCR:			ER NON-CONFORM	IANCE (NO	CR)				
DATE	STEP	Description of NC		ction B	Verifi	cation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sigi Da		ion C	Chief Eng	QC Inspector
					·				
· 									
] .								

Work Order ID 56844

March 10, 2010 3:53:24 PM



Page 3

Item ID:

D3805-043

Accept

Setup Start

Stop



Revision ID:

Item Name:

Wearplate Assembly Fwd, High Gear

Start Date:

10/03/2010

Start Qty: 2.00

Required Date: 17/03/2010 Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date:

Tooling:

0.00

Date:

Run Start



QC: _____ Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID

150



Small Fab

Small Fab

Operation **Description**

Set Up/ Run Hours **Draw** Number

Plan Draw Rev. Code Accept Reject Qty Qty

Reject

Insp. Number Stamp

1- Bond D3807-3 gasket to inner surface of wearplate using a thin layer of 3m 1300/1300L scotch grip adhesive as per dwg BATCH: M1/3174

160



Quality Control

QC5- Inspect part completeness to step on W/O

170



Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

Memo

58518

Cerefolio (5)

	1								
W/O:			W	ORK ORDER CHANG	ES		·		
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
1									,
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA	:	_ Date: _	
Res		esolution:							
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)			
DATE	STEP	Description of NC Section A		Corrective Action Section		Verific	ation	Approval	Approval
DAIL	JILF		Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Chief Eng	QC Inspector
									-
									; ;
		·							
									ļ.

Work Order ID 56844

March 10, 2010 3:53:24 PM

Required Date: 17/03/2010



Page 4

Item ID:

D3805-043

Accept

Setup Start



Revision ID:

Item Name:

Wearplate Assembly Fwd, High Gear

Stop

Start Date:

10/03/2010

Start Qty: 2.00 Req'd Qty: 2.00

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Run

Sequence ID/ Work Center ID

180

Operation **Description**

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours** Draw Number

Draw Plan Rev. Code

Accept Qty Qty

Reject Reject Number

Insp. Stamp

Memo

0.00

Quality Control

0.00

W/O:	**-		VORK ORDER CH	RK ORDER CHANGES							
DATE	STEP		PROCEDI			ANGLO	Ву	Date	Qty	Approval Chief Eng./ Prod Mgr	Approval QC Inspector
				•							
Part No		PAR #: _									
NCR:					DER NON-CONFO						
DATE	STEP	Description of NC Section A		nitial nief Eng	Corrective Action Action Descrip Chief Eng	Section B	Sign Date			Approval Chief Eng	Approval QC Inspector

Picklist Print

March 10, 2010 3:53:29 PM

Work Order ID: 56844

Parent Item:

D3805-043

Parent Item Name:

Wearplate Assembly Fwd, High Gear

Comments:

IPP RevB: add transfer drill wearplate to bar DD 09.11.05 verified by:EC



Start Date: 10/03/2010

Required Date: 17/03/2010

Page 1

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status	
D3805-3	III	Manufactured	No		100	Each	1.0000	2.0000	7			

Plate

D3806-3

D3807-3

Gasket

B 56863 XH

Manufactured No

5686424

Manufactured

Location

Main Warehouse

ST

Warehouse

46930

52852 X1

150

Each

2.0000

0.0000

2.0000

2.0000

Warehouse

Loc Qty

Loc Qty

Loc Code

Location

Main Warehouse

ST236B


-100

356865 3D


Loc Code

Bro 10-4-78


	•											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							-					
				· · · · · · · · · · · · · · · · · · ·								
										,		
Part No) :	PAR #:			NC	R: Yes	No DQ	A:	Date: _			
		esolution:										
NCR:			WORK OR	DER NON-CONF	ORMANC	IANCE (NCR)						
DATE	STEP	Description of NC		Corrective Action	Section B		Verific	cation	Approval	Approval		
DATE	SILP	Section A	Initial Action Des Chief Eng Chief E		iption ——————	Section C		Chief Eng	QC Inspector			
										-		
									ı			
								j				
		·				·						
				·	. "							




	•											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									į			
Part No			Fault Cat		NOS							
Part No: PAR #:												
	ne:								Date:			
NCR:			WORK ORL	DER NON-CONFORM	ANCE	(NCH)						
DATE	STEP	Description of NC			tion B		Verific	ation	Approval	Approval		
	0,2,	Section A	Initial Action De Chief Eng Chief			Sign & Date	Section C		Chief Eng	QC Inspector		
								-	*:			
									1			
									·			
					Ì							




	•											
W/O:	N/O:			WORK ORDER CHANGES								
DATE	STEP	PROC	EDURE CH	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
	·											
					·				;			
Part No	•	PAR #:	_ Fault Ca	tegory:	NCI	R: Yes	No DQ	4 :	Date:	Mark The Co.		
Resolution:			_ Disposit	tion:	QA:	N/C CI	osed:		Date:	·		
NCR:		W	ORK OR	DER NON-CONFO	RMANCE	(NCR)					
DATE	STEP	Description of NC		Corrective Action	Section B		Verific	ation	Approval	Approval		
DAIL	JILI	Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign & Date	Section		Chief Eng	QC Inspector		
			·	·					·	-		
							!					
							·					
								,				




		— - - -								
W/O:			WC	ORK ORDER CHANG	ES	PARIS 11-11-11-11-11-11-11-11-11-11-11-11-11-	- 1		<u></u>	
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				•						
								,		
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A :	_ Date: _		
	Resolution:		Disposition	n:	_ QA: N/C C	losed:		Date:		
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCI	(NCR)				
DATE	STEP	Description of NC		Corrective Action Secti		Verific	cation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date		on C	Chief Eng	QC Inspector	
									-	
								' 		
						·	!			
						·				
								·		




W/O:			W	ORK ORDER CHANG	ES			***					
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								::					
						· · · · -							
						•							
								· · · · · · · · · · · · · · · · · · ·					
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A :	_ Date: _					
Resolution:			Dispositi	on:	_ QA: N/C CI	osed:		Date: _					
NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
DATE	STEP	Description of NC	Initial	Corrective Action Section		Verific		Approval	Approval				
····		Section A	Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector				
									-				
													
 													




W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	o DQA: Date:		
Resolution:			Dispositio	_ QA: N/C C	losed:	Date:			
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	₹)			
DATE	STEP	Description of NC	Corrective Action Section B			Verification			Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	& Secti		Approval Chief Eng	QC Inspector
									-
						·			
								i	
									1.



	•						_		
W/O:			W	ORK ORDER CHANG	ES			******	
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								ı.	
-									
	,								
Part No:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	DQA: Date:		
	Res	olution:	Dispositio	_ QA: N/C Clo	osed:	Date:			
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description			Sign & Section (Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Secti	ion C	Chief Eng	QC Inspector
									-
						·			
	1 1		1		1	1		ı	I



	•										
W/O:			WO	RK ORDER CHAN	GES						
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							·				
			14 54								
Part No:					NCR: Yes No DQA: Date:						
Resolution:			Disposition: Q			QA: N/C Closed:				_ Date:	
NCR:			WORK ORDE	ER NON-CONFORM	IANCE (NCR))				
DATE	STEP	Description of NC			ection B		Verification		Approval	Approval	
	-	Section A	Initial Chief Eng	Action Description Chief Eng	S	ign & Date	Section		Chief Eng	QC Inspector	
										-	
							·				
					'						



W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								,				
						·						
		PAR #:	Fault Categ	ory:	NCR: Yes No DO)QA: Date:				
		solution:	Disposition:					Date:				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	R)		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng			cation ion C	Approval Chief Eng	Approval QC Inspector			
			Officer Eng	Criter Eng	Date				-			
					-							
								1				
							•					
]		1			- 1		1				